





## Analogue multimeter selection guide

	 C-A 5001	 C-A 5003	 C-A 5005	 C-A 5011
Analogue	■	■	■	■
Digital				■
Anti-parallax mirror	■	■	■	
4,000-count display				■
Backlighting				■
TRMS AC+DC measurement method				■
Max				■
AC and DC voltage up to 1,000 V	■	■	■	■
Low-impedance calibre (LowZ)	■	■	■	
AC and DC intensity	■	■	■	■
Intensity via clamp	■	■	■	
µA calibre	■	■	■	
5 A calibre	■			
10 A calibre			■	■
15 A calibre		■		
Resistance	■	■	■	■
Audible continuity	■	■	■	■
Frequency				■
dB	■	■	■	■
Fuse test LED	■	■	■	■
Voltage presence LED in ohmmeter mode				■
CAT III 600 V	■	■	■	
CAT IV 600 V / CAT III 1,000 V				■
Page	20	20	20	21